JOB NO. 4802 BARGE: ETT113

BASF 8/95



INVOICE

REMIT PAYMENT TO: AIR LIQUIDE AMERICA CORPORATION P. O. Sox 200411 HOUSTON, TEXAS 77216-0411

TERMS: NET CASH 30 DAYS

NAVOICE INCRIRES CALL: (713) 896-2100

AIR LIQUIDE AMERICA CORPORATION
P.O. 80X 3047
HOUSTON, TEXAS 77253
PHONE (713) 968-0333

Please Return One Copy Of This Invoice With Your Florrittance 38249300 HERCULES OFFSHORE DRILLING ETT 113 (INS RGN ONLY) MARINE DV BARGE PURGE DRAWER OF FREEPORT 77541 T SURFSIDE

TX

CUSTOMER DADER NUMBER: CUSTOMER REO, NUMBER TO DATE SHIPPER FAON. CREDIT INVIDICE DATE: INVOICE # 1802890387 LARRY BOLLINGER E8 15 95 002978 118 118 38/31/95 910704

EACH CYLINDER GALLON	B. CUBIC FEET	F. FEET C. P/100 K. LITER	P. PAIR M. P/1000 H. OLNICE	2,	338.75	E	XEMPT			-60	2	338-7
j	UNIT OF MEASUR			and and	TOTAL SERVY	A Service	TAGE	, PREIG	ную	enge A		SOUNA P
}		1:43	o Torres or see	# A #	cirllege	To Sec	a Tou	म <i>ेंदे</i> केस	Ġī,	, j.:	•	
								·				
2.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00							Arm t Si George				india a se	
	IMPERTANT SHEETS FOR CALL US AT	THE P	RODUCT (S)	LISTE	D- IF Y	OU NEE				ETY DA OPIES	TA PLEAS	5
-						2+50		.500C				3-7
94928 86714	PUMPER MIL LICUID NIT GEVT REGUL	EAGE ROGEN	COMO: TAM	- =	110	154.90 009.00	1.	8300 1503	E C		1	270+0 265+0
	SERVICE CH PUMPER HOU					1.00 2.50	4	ບດອ ວ ເພື່ອ ວວ ອ				650-Q
PARTAPA	1200	> > ORSCHIP	THOM IS	3 A 5 L	CHARTET	K SHIPPEU	S. SCHOLL A	FICE (24	mecount	No.	armiti Pri

HER 06141

49M NO. W. SUP (Rev. 1/34)

RECEIVING ADDRESS: 3802 West 11th Street Houston, Texas 77008 STATEMENTS ISSUED ONLY ON REQUEST

PAYTHIS AMOUNT

*/′ CED 4	4 /OF OO		070 1701	-50 0.30	ELUIG V		П	TT 45 4				
DATE ORDERED		: JJHN (22)	AIR LIQU	Manakan	CH WLY		راروه ي الم		O. a	SH	-3/3 -1	DER NO.
8-14-95		04	•		•			BANCHE,	/# G .	118-	00:	2978
WATTENBY	<u> </u>			Industrial							INVOICE D	
8-15-95		Ge	meral Office: P Remit Paymen	40, BQX 3047 t to: P.O. BOX :	HOUSTON 200411 H	I, TEX DUST	(AB 77253 7 'ON, TEXAS 7	713/868-00 77216-041	133 1	-	INVOICE	NO.
						1						
\$ Account No	• <i>5</i> 8249	300	Room St	Salle		Ş	Customer	HERC	ules &	i-ESH	RE	
S Account No	198244 Hercult	')/46nox	THE PROPERTY OF	'9	<u> </u>	Location .	SUR F.	SIDE D	الزيمت	- Kü 🗓	- ()
Address	Drawer	٥	•	~:-								
i City Fre	epo(+		1X	21°	541	Ğ	CitySue	45,05	ng & Ba	State 7	¥	Zi p
480⊃89E	AER CROER NO.	· · · · · ·		To like			DRIGH	FROM	70	TAXEA	CREDI	TAPPROVAL
	3367 1. PRE	IAB BI	LIGHT		Dec.	TAAL	118	1/8	1/8			
WARNING	2. CUS	TOMERI	CUSSION WAS HAS RECEIVED	A COPY OF SA	ETY PAECAL	JTION	8.			INITIAL INITIAL		ARNING
THE UNDERSTONES C	USTOMERNADREE	10 10	HASE INDUSTRIES	S' GENERAL TERM	8 AND CONCIT	ions c	F SERVICE INCL	JOHN THOSE	appearing on ti	HE REVERSE H	EREOF:	-
AUTHORIZED SIGNATU	you !	7	degree _			11	man.		DATE	~ 		
QUANTITY		_	-0 -		THILE				· · · · · · · ·	UNIT	BI	
ORDERED	PART NO.	Secrie	e Charge	DESCRIPT	ION			QUANTIT	Y SHIPPED	COST	╼┼┼╎╩	AMOUNT
	1949a8	02.10	- 1 - 1	1				_	<u> 1</u>	650.0	<u> </u>	650.0
00	14928	Time C	vedurių sečirių	25				2	۵.	۵۰.۵سا	5 E	150.0
	1990	Time C	harges Trenspo						(100,00	- - - 	 150.0.
		Winas									- -	
lap	14 1 28	MINERAL	le Pumper 15 E)				16	Ó	1.80	Ē	270.0
		Parient	e Transport	•								
		Nitrog	en Charges			_					- -	
	714		110	2,000				110	000	1.15	C	13650
		•								j	- [[
		i		,							71	
			·									
										·		
	344	COVERA	IMENT AGENCY	REQUEATORY	COMPLIANC	ŧ ĠW	MOE 2.5	a	.5	1.60	E	3.76
		Suble										
		Tex	·							<u> </u>	-+-	2338.7
											$\perp \perp \perp$	
		Total] .		
		<u> </u>										
Credit 10	<u>2</u>	O 210 Pr	recoure Teet/purgo	<u></u>			eneration D	240 Dryout	D 250 Seldoni			@ 260 Ship Pur
EQUIPMEN	$\Pi_{i}^{A_{i}}(\cdot,\cdot,\cdot)^{a_{i}}$		UNIT 1	TYPE	UNIT	2 -	TYPE	UNIT	3 TYF	1U ≥ ⊡°	VIT 4	TYPE
Unit No. & Type			3,44	MINI HA								
Date & Time Starte	ed		8-15-95	1900								
Date & Time Comp	eted		8-15-95	2130								
TOTAL Na UNIT HO	OUR8		. Pro 18	2.5								<u> </u>
Rate SCFM			700 -	1500	<u> </u>							
TOTAL N2 USED			at in parati-									
12 P. S. S. S. S. S.				EQU	IPMEN	ΤM	ILEAGE			2 3	32 - 50 6 6 6 6	A STATE OF
Roundtrip Miles Fi	rom: 11 C		4.00	यह प	¥							<u> </u>
TOTAL CHARGEA		50		of Units / \$	150 R	771	,		-			
	11850多年發展			TRANSPO				TIME	of the sale	Parties in	J. 1. 185	
			· · · · · · · · · · · · · · · · · · ·						·			
Roundtrip Miles Fr												
TOTAL CHARGEA Total Transport Tire			X 140	of Transports								
Total Chargeable												
I hereby soknowledge (THE TOTAL STATE OF	post phro poor our	mpielag.	Bio	Three Opera	tore:	trn Dêw	~/		
Authorized Signa			الأكراني	de.					7 FA L'ALAGA	-		
Total digital	<u> </u>	40.1	Date	2.14.0	-	Ren	narks:					
11000 13 14/1	^		Date 2	70		1				HER (6142	_
Ponel	Ciam	<i>-</i>	∽/									
Dia Thoma I M S R	enrecentative		# <u>'</u>						-	_		



West Little York Office Houston, Texas FAX Number (713) 896-2367

Date:	A- 11-96 Total # of P	
	(Includin	g Cover Page)
ar'		
Message To	D :	
		-
	Name:	•
	Company: Nercules Offshore	
	FAX Number: 409_ 233- 6375	
Message Fr	om:	
	Denise Morgan	
	Industrial Nitrogen Service Region	بيتر.
Notes:	Per your request.	
	1	

 $(\mathbb{R}^{n} \otimes \mathbb{R}^{n}) : \mathbb{R}^{n} \otimes \mathbb{R}^{n} \otimes \mathbb{R}^{n} \times \mathbb{R}^{n}$

SHIPPING ORDER

WRIT	ORDEREC - / 4/ - TEN BY SHIPPED	95	Ge	neral Office: F	Merchant Industrial 20. BOX 3047 1 to: P.O. BOX 2	Nitrog Houston	en S N, TEX	Services (AS 77253	71 3/868-0 3	333	118 -	O O	2SEDATE	378
SOLO FO	Account Custo Addre	int No. mer ss		State	Zip	HERCL SURFS ETT 11 Rendered p.	ILES OF	Eg						
		USTOMER ORDER NO.		<u> </u>	ORDERED BY			0RIGIN 118	FROM 1/8	1/8	TAX %	ÇA	EDIT A	PPROVAL
THE	VARN INDERSIG ORIZED SI	2. CU MED CUSTOMER AGREE	STOMER	HAS RECEIVED	HELD & SAFETY A COPY OF SAF S'GENERAL TERM!	ETY PRECA	UTION	s	LUDING THOSE	APPEARING ON T	111111111		VAF	RNING
QÜ	ANTITY	T	Τ		DESCRIPT			·	CHANTE		ÜNIT	Į.	Ţ	AAAOUINT
	DERED	PART NO.	Service	e Charge	DESCRIPT	IUN			QUANTI	Y SHIPPED	COST	- †	^	AMOUNT
		<u></u>		harges Pumper					 			-		
				Charges Transpo	<u> </u>				1		<u> </u>			
		_			···									<u> </u>
			Mileag	je Pumper 3 Z I)				<u> </u>		L .			
			Mileag	e Transport									-	
		·· - ·-	Nitrog	en Charges									М	
			╁╌	110	7,000						}	+		
					-									
			GOVE		NCY REGULATOR	RY COMPLU	WCE (Z.SOWK						
			1	lai					<u> </u>]			
			Tax	;					-		}		1	
			Total											
Credit			□ 210 Pr	essure Teal/purge	□ 220 Cool d	Jown 🗆 2	30 Reg	eneration ()	240 Dryout	☐ 250 Seltdom	0 270 P	peline	۔۔۔ا	280 Ship Purge
EC	UIPN	/ENT		UNIT 1	TYPE	UNIT	2	TYPE	UNIT	3 TYF	E UI	VIT 4		TYPE
Unit	No. & Ty	D6		3148	Min HR				•			_		
_	& Time !			8-15-95	1900									
		Completed		<u>8-15-95 </u>	2130	 _	_		<u> </u>	-			+	
_	SCFM	IIT HOURS			<u>1.5</u>	 			<u> </u>					
	AL N ₂ US	SED		700-	1200	 -	•							
ŀ	78 Yes 3	كالمناك المستناد		ty ji ku di	EQU	IPMEN	ΤM	ILEAGE	- 10 √ ~ . ± ′		1. V-18.			· · · · · · · · · · · · · · · · · · ·
Rour	ndtrip Mi	iles From: 11 %		LAPOR										
$\overline{}$		GEABLE MILES	50		of Units / = .	150 R	71						-	
	1				TRANSPO			GE AND	TIME ***	egar jage		A. Carlo	Å.	
		les From:												
		RGEABLE MILES ort Time On Site	-	X No.	of Transports									-
	-	able Transport Time											-	
		ledge that the above info		yreot, and the sen	vices bave been cor	npleted.	Big	Three Opera	ators: C	mEler	√			
Autr	orized S	Signature 🗸 😾	41	Su II	idea	- (
Title	-	3		Date -	7-4-60		Ren	narks:						
Big 1	Three I.N	J.S. Representative	'ERO	d							HER	061	44	

BIG THREE MERCHANT GASES AND EQUIPMENT, INC. GENERAL TERMS AND CONDITIONS OF SERVICE

The service consists of delivery of nitrogen or oxygen to the Customer at the Customer's use point (the "size") by means of connections furnished by the Customer, the quantities, pressures and times of delivery being subject to the Customer's directions. The Customer at all times has complete charge, custody, control and responsibility for all tubing or other connections or equipment furnished for the receipt of delivery of the nitrogen or oxygen for the Customer's unit, the conditions within the unit production gipe or other equipment about or in the unit and the premises about the unit.

In consideration of the service and product prices as set out in its current price schedule, it is understood that the services and products of Big Three Industries, Inc., ("Big Three") is offered, furnished and sold only under the following terms and conditions:

- (1). A responsible representative of the Customer must be present at all times to designate and provide the point of connection into which nitrogen or oxygen is to be delivered and to designate the quantities of nitrogen or oxygen to be delivered, the pressures at which the same shall be delivered, and the times at which the same shall be delivered.
- (2) If, in order to gain access to or to return from the site, it is necessary to repair roads or bridges or to provide tractors, vessels or other special means of transportation for Big Three equipment, material or personnel, such shall be arranged and paid for by the Customer. The Customer shall be fully responsible for and shall indemnify Big Three against any loss arising as a result of any damage to or loss of any of Big Three's equipment or materials while same are being transported to or from the site by means furnished or arranged for by Customer or while such equipment or materials are being loaded upon or attached to any special means of transportation furnished or arranged for by Customer.
- (3) Purity of all product furnished under this Agreement shall comply with Compressed Gas Association standards. Big Three's only liability or obligation in respect to any product which fails to meet the standards provided for herein shall be to replace such product at Big Three's expense. BIG THREE MAKES NO WARRANTY OF ANY KIND. EXPRESSLY OR IMPLIED, EXCEPT THAT PRODUCTS DELIVERED HEREUNDER SHALL CONFORM TO COMPRESSED GAS ASSOCIATION STANDARDS UNLESS OTHERWISE SPECIFIED. BIG THREE SHALL NOT BE LIABLE FOR DIRECT, INDIRECT OR CONSEQUENTIAL DAMAGES OF ANY KIND OR FOR DAMAGES ARISING FROM THE PRESENCE OR USE OF PRODUCTS HEREIN CONCERNED, WHETHER USED SINGLY OR IN COMBINATION WITH OTHER SUBSTANCES. THERE ARE NOT ANY WARRANTIES WHICH EXTEND BEYOND THE DESCRIPTION ON THE FACE HERE. Customer shall and does hereby indemnify and hold Big Three harmless against any and all-loss, cost, damage, liability, claim or expense, including (but not-limited to) attorney's fee, arising out of injury to or death of persons, or damage to or destruction of Customer's use thereof.
- (4) While Big Three will render the services contracted for to the best of its ability, it does not guarantee any results and, except in the case of gross or willful negligence on-its part, shall not-be-liable or responsible for any damage to the site or any equipment located at the site or for any loss or damage whatsoever (including injury to or death of person or property damage) growing out of or in any way connected with its operations and Customer shall absolve and hold Big Three Industries, Inc. harmless against all liability for any such loss or damage sustained or incurred by Customer or any third party irrespective of the cause.
- (5) All statements rendered for services performed by Big Three shall be paid at its offices in Houston, Texas within thirty days from date of statement. If not paid within thirty days, the unpaid amount of such bill shall bear interest at the rate of ten per cent per annum and, if necessary to be collected by an attorney, an additional amount shall become due and payable as reasonable attorney's fees
- (6) This contract shall be construed in accordance with the laws of the State of Texas:
- (7) All of the preceding terms and conditions shall apply in favor of any manufacturer of supplier of any equipment Big Three may use in the performance of all performance of any of its services.
- (8) Prices listed in Big Three's current schedule do not include sales or similar taxes and it reserves the right to add such taxes, if any, to its published prices. Any tax based on or measured by the charges made for, or the cash receipts from the sale of materials or products or the rendering of services shall be added to the stated price.

Fallure to enforce any or all of the above terms and conditions in a particular instance shall not constitute a waiver of or preclade subsequent enforcement.

No employee is empowered to after or waive any of above terms and conditions.

Prices are subject to change without notice.

BIG THREE MERCHANT GASES AND EQUIPMENT, INC. Bouston, Texas

SHIPPING ORDER

DATE ORDERE	<u>n</u>	-	—	*** /					^	- 9	IIDDEDS	CON	ED NO			
	1	80	g Three T	Merchant	: Gases	ai	ed Equi	pment.	nc.		118 - 002978					
WAITTEN BY			· 	Industrial	Nitroge	n S	Services			1.0	<u> </u>	J_ Æ DA	<u> 710 </u>			
		Ge							333	<u></u>		<i>-</i>	· -			
DATE SHIPPED	General Office: P.O. BOX 3047 HOUS Remit Payment to: P.O. BOX 20041 Account No. Customer						ON, TEXAS	77216-041	1	·	INVOI	CE N) .			
	General Office: P.O. BOX 3047 HOUST Remit Payment to: P.O. BOX 200411 Account No. Customer Address										_					
0						S			د و ښکان		ئے منبقون					
L Custo						1	Location	ちの後手。	8122 A	7555						
D Addr	ess					P	Unit Name	- * * * /	13	_						
T City		•	State	Zip		ŏ	Services f	Rendered 🔑	1.35€ 184			2				
Ĭ						~	City/	15.0c.		State 7	>	- 2	Zip			
	CUSTOMER ORDER NO.		_	ORDERED BY		<u>. </u>	ORIGIN	FROM	TO :	TAX %	CF	REDIT	APPROVAL			
							118	11.2	118							
WARN				HELD & SAFETY						INITIAL	- 7	NΑ	RNING			
	GNED CUSTOMER AGREE			A COPY OF SAF S' GENERAL TERMS				LUDING THOSE	APPEARING ON T							
x A	1		, , , , , , , , , , , , , , , , , , , ,			_										
AUTHORIZED S	IGNATURE		· · · · · · · · · · · · · · · · · · ·		TITLE				DATE				····			
ORDERED	PART NO.			DESCRIPTI				OHANTI	TY SHIPPED	UNIT	Į,	Ţ	AMOUNT			
CHUCKEU	PART NO.	Service	ce Charge	DESCRIPTI	iON .			COANT	I I SHIPPEU	COST	+	ļ.	AMOUNT			
	<u> </u>	1	•	_					_	L						
		Time (Charges Pumper	20												
	 	Time (Charges Transpo	<u>د ے</u> n				 		 	+	+				
		//		••				1		}	- 1	'				
		Milea	ge Pumper i.≲ č													
	 -	Miles	ge Transport	<u> </u>				 		 	-	┼	-			
				-								-				
-		Nitrog	en Charges				•									
		 		2 00 0				 				╄				
] .			- [┨				
								_			T					
	 	 		-				1		 	+	╄				
		Ì										Į				
		GOV	ERNMENT AGE	NCY REGULATO	EV COMM IN	MAC.	***********									
		Subto								 		╄				
		50010														
		Tax									\neg	Τ				
		Total						1		,	\dashv	╄				
	1	'0'						1			-					
		-										•	···			
Credit		☐ 210P	ressure Test/purge	□ 220 Cool d	town - 23	X) Reg	eneration D	240 Dryout	C 250 Saltdoni	• □ 270 F	ipeline	0	280 Ship Purp			
FOUID	MENT		UNIT 1	TYPE	UNIT	9 i	TYPE	UNIT	3 TYI	PE II	NIT.	4	TYPE			
				1	ORU			UKIA			VIII .					
Unit No. & Ty			3:43	M. 9. 11 R	<u> </u>	_						4				
Date & Time			8-15-75	10-0	↓	_										
Date & Time	Completed		8-15-95	2150	<u> </u>											
TOTAL N ₂ U	NIT HOURS	ا		₹.5		[
Rate SCFM			700-	1500												
TOTAL N ₂ U	SED				·				•							
4 3 4 3	(1) 表现的 (1) A	- 31 - 11 1 1 1 1 1 1		FOL	IPMEN	ΤM	ILEAGE	13		1.00	r fall o		¥			
											•					
Roundtrip M	•		Two Canal													
	RGEABLE MILES 1		∵≝⊕XNo.	of Units / =	150 R	T.#\										
	Part of the second			TRANSPO	RT MIL	EΑ	GE AND	TIME :	1000 0	1860	1479					
Roundtrip M	diles From:															
			VII	of Tuesca = ==	<u> </u>				<u>.</u>							
	RGEABLE MILES		X No.	of Transports												
	ort Time On Site						•									
	eable Transport Time		·	<u> </u>		,										
i nereby acknow	wiedge that the above infon	mation is d	orrect, and the sen	uces have been con	npletad.	Big	Three Opera	ators: 🏑 🦳	وجاني مح وود المع	^/						
Authorized	Signature	/	<u> </u>	<u> </u>												
Title			Date			Rer	narks:									
	of Same	- 17	ωI			<u> </u>										
Big Three I.I	N.S. Representative	<u></u>	· / /			-				HER (614	16				

BIG THREE MERCHANT GASES AND EQUIPMENT, INC. GENERAL TERMS AND CONDITIONS OF SERVICE

The service consists of delivery of nitrogen or oxygen to the Customer at the Customer's use point (the "site") by means of connections furnished by the Customer, the quantities, pressures and times of delivery being subject to the Customer's directions. The Customer at all times has complete charge, custody, control and responsibility for all tubing or other connections or equipment furnished for the receipt of delivery of the nitrogen or oxygen for the Customer's unit, the conditions within the unit production pipe or other equipment about or in the unit and the premises about the unit.

In consideration of the service and product prices as set out in its current price schedule, it is understood that the services and products of Big Three Industries, Inc., ("Big Three") is offered, furnished and sold only under the following terms and conditions:

- (1) A responsible representative of the Customer must be present at all times to designate and provide the point of connection into which nitrogen or oxygen is to be delivered and to designate the quantities of nitrogen or oxygen to be delivered, the pressures at which the same shall be delivered, and the times at which the same shall be delivered.
- (2) If, in order to gain access to or to return from the site, it is necessary to repair roads or bridges or to provide tractors, vessels or other special means of transportation for Big Three equipment, material or personnel, such shall be arranged and paid for by the Customer. The Customer shall be fully responsible for and shall indemnify Big Three against any loss arising as a result of any damage to or loss of any of Big Three's equipment or materials while same are being transported to or from the site by means furnished or arranged for by Customer or while such equipment or materials are being loaded upon or attached to any special means of transportation furnished or arranged for by Customer.
 - (3) Purity of all product furnished under this Agreement shall comply with Compressed Gas Association standards. Big Three's only liability or obligation in respect to any product which fails to meet the standards provided for herein shall be to replace such product at Big Three's expense. BIG THREE MAKES NO WARRANTY OF ANY KIND, EXPRESSLY OR IMPLIED, EXCEPT THAT PRODUCTS DELIVERED HEREUNDER SHALL CONFORM TO COMPRESSED GAS ASSOCIATION STANDARDS UNLESS OTHERWISE SPECIFIED. BIG THREE SHALL NOT BE LIABLE FOR DIRECT, INDIRECT OR CONSEQUENTIAL DAMAGES OF ANY KIND OR FOR DAMAGES ARISING FROM THE PRESENCE OR USE OF PRODUCTS HEREIN CONCERNED, WHETHER USED SINGLY OR IN COMBINATION WITH OTHER SUBSTANCES. THERE ARE NOT ANY WARRANTIES WHICH EXTEND BEYOND THE DESCRIPTION ON THE FACE HERE. Customer shall and does hereby indemnify and hold Big Three harmless-against any and all-loss, cost, damage, liability, claim or expense, including (but-not limited to) attorney's fee, arising out of injury to or death of persons, or damage to or destruction of property. In the products of the products concerned hereunder, or Customer's use thereof.
 - (4) While Big Three will render the services contracted for to the best of its ability, it does not guarantee any results and, except in the case of gross or willful negligence on its part, shall not be liable or responsible for any damage to the site or any equipment located—at the site or for any loss or damage whatsoever (including injury to or death of person or property damage) growing out of or in any way connected with its operations and Customer shall absolve and hold Big Three industries, Inc. harmless against all liability for any such loss or damage sustained or incurred by Customer or any third-party irrespective of the cause.
 - (5) All statements rendered for services performed by Big Thine shall be part as its offices in Househit. Decay in the thirty days, from date of statement. If not paid within thirty days, the unpaid amount of such bill shall bear interest at the rate of ten per cent per annum and, if necessary to be collected by an attorney, an additional amount shall become due and payable as reasonable attorney's fees.
 - (6) This contract shall be construed in accordance with the laws of the State of Texas.
 - (7) All of the preceding terms and conditions shall apply in favor of any manufacturer of supplies of any equipment Big Three may use in the performance of the speed perfo
 - (8) Prices listed in Big Three's current schedule do not include sales or similar taxes and it reserves the right to add such taxes, if any, to its published prices. Any tax based on or measured by the charges made for, or the cash receipts from the sale of materials or products or the rendering of services shall be added to the stated prices.

products or the rendering of services shall be added to the stated prise.

Failure to enforce any or all of the above terms and conditions in a particular instance shall not constitute a waiver of or preclude subsequent enforcement.

No employee is empowered to alter or waive any of above terms and conditions.

Prices are subject to change without notice.

P. O. Drawer O . Freeport, Texas 77541

INVOICE NO. : 3098-95

DATE

: August 30, 1995

Job No.

: 4802A-1

Location

: Freeport

TO:

BASF

602 Copper Road Freeport, TX 77541 PLEASE REMIT PAYMENTS TO:

11011 RICHMOND

SUITE 500

HOUSTON, TX. 77042

PO#F91392

: Net 30

ع.د.

FOR:

Service to ETT113 as follows:

Set up equiament Strip out all free product Blow cargo pipeline and stripping system Vacuum blow dry cargo tanks Sweep powder rust from cargo tank floors Wash and strip deck around engine and headers Pressure test cargo pipeline to 40# PSI Clean off deck Remove equipment Close barge

Leadman 6 S/T Labor: Ð 33.50

Journey 30 S/T @ 31.00

Equipment: Compressor 8 44.00

Air movers 20 ø 5.00 Vacuum 4 0 20.00 Hand hose 10.00

Material: 27.20 5.44

TITAL AMOUNT DUE

1,735.64

201.00

930.00

352.00

100.00

80.00

40.00

32.64

ARRIVED: COMPLETED: 8/15/95 8:00 a.m.

8/15/95 4:00 p.m.

PHONE: {409} 233-6371 .

HER 06148

MARINE SERVICE CORF. FREEPORT, TEXAS FOREMAN'S DAILY TIME REPORT JOB NO 480 A A DATE 8-15-95 CLASS HO. ETTIB	Strip + 610w								
BADGE NAME		- "				<u> </u>	i		
53 CLAUDIO DUARTE	/6	- ;	<u></u>	, -		:			(
70 JUAN RIVERA	1						_		ι
60 JOE OLIVAREZ	/6		-	 					
579 LUCIO NAJERA	6		 						,
									
		:							
			<u>.</u>					_	
								-	
507 IGNACIO SILVA	7 <u>/6</u>				:	:			(
					 				_
			 	 					 _
			 	<u> </u>					
08 SAM PETTIT	1/4		 		_	HF!	 R 0614	10	-
TOTAL HOURS						1	1 00 12	⊦ ∀ 	31
SIGNED FOREMAN	CODED AND EXTENDED. BY		 	 6	IP PR OVE(·			



DATE: 8-15-95

Office: (409) 233-6371 Fax: (409) 233-6375

FINAL CHECK LIST

BARGE: <u>F</u> + + - 113	
BLND NUMBER CHECKED 2 REPLACED GASKET YES NO 2	
GATE VALVE NUMBER CHECKED 6 REPLACED GASKET YES NO:	-
PLUGS NUMBER THECKED / REPLACED PLUG YES NO	-
CHECK VALVE NUMBER CHECKED WA REPLACED GASKET YES NO	
DEEPWELL BLIND NUMBER CHECKED NO REPLACED GASKET YES NO	
BELOW DEAK CARCO PARTITUR OF THE NUMBER / PROTECTE OF CLOSER AND	
BELOW DECK CARGO PIPELINE BLIND NUMBER / REPLACED GASKET YES NO	
BELOW DECK CARGO PIPELINE BLIND REMOVED YES NO	
DRIP PANS VALVES: CLOSED BY SILVA	
DRIP PANS COVER CLOSED BY MA	
COMTAINMENT AREA PLUG OR VALVES: CLOSED BY SILVA	_
AIR TEST CARGO LINE - 40psi - USING SOAP	
SIGNATURE OF TESTER: Claude Dunt	
WITNESS:	

CHECK VALVE CASKET WILL BE REPLACED
AIR TEST IS LAST THING TO BE DONE BEFORE RELEASING BARGE.



Strength through environmental awareness and customer service

P.O. Drawer O Freepon, Texas 77541 Ottico (409) 233-6371 Fax. (409) 233-6375

EQU I PMENT	HOURS USED	HOURLY RATE	TOTAL PRICE
COMPRESSOR	55	44.00	
AIR MOVERS	20	5.00	
VACUUM	3	20.00	
BOILER		80.00	<i>1</i> 2*
HAND HOSE	3	10.00	
BUTTERWORTH		10.00	
2" STRIP PUMP		12.00	
3" DIESEL PUMP		14.00	
4" ELECT PUMP		15.00	
			,,
CRANE		130.00 ^	
CHERRYPICKER		50.00	
FORKLIET		20.00	
TUC BOAT		80.00	
WELD MACHINE		15.00	<u>,</u>
CUTTING RIG		6.00	
WORK BARCE		35.00	
HAUL OUT		1100.00	

DATE: 8-15-85 JOB NO: 4802 BARGE NAME: 2= 1-13

CONTROCTO CONTROCTOR AND A CONTROL OF CONTRO

טא ווטר	·— ;—4-2	102 A CUSTOMER:	BASE	ENTILS ETTILS
ាប់នេះស្រ	1:			
	0/1	<u> </u>		ÿ
Latiniegy)	~ ~ 	P 51.75		
	0/t	<u> </u>		301
JOSEPHER		30 24 15 40,00		
	0/r	8 4 31.00		· 558 930,80
		E 44.25		
THE TOPAL	·:	gal e .a	s.	
			•	
PATERITAN	·: <u>37</u> ,	70 brnz 50.s	5,44	- 31, 6H
MA SECURE	TERIAL:	Pf. US 20.8		
				·
Ա <u>ՂՍ</u> ՂԴ:		2		The second section
	COMPUTED	**************************************	44.00	352.00
	ATA HOVE	<u> 30</u> °	5.00	100
	PORKLIPT		26.60	
	יוועניניניני		00.60	
	STEAM RUC		00.00	
	VACULA		M.Ou	€ 80 °
	HAND HOSE		10.00	34. AD
	WEDDING WATER		15.00	
	CHANE		.0.00	A
	PLATED TRUCK	· · · · · · · · · · · · · · · · · · ·	0.00	
	O" CAS PUMP			**************************************
	7. Suggester		4.00 2.00	
	บบเมลงรัฐเราม		ů.ůů	alan di Primasa dan masan masan san sanaga da sanaga da sanaga ang ang ang ang ang ang ang ang an
	4., EXTECT, LIMIT		5.00	
	LORGE TARCE		5.00	
	CONTING THE	and the second second	ũ.CO	——————————————————————————————————————
	HAUL OUP		0.00 / 1Xiy	
	100		•	
aarvaa:		COMPLETED:	บัยตัวสถานั้น:	
	,			
1306215 <u>_</u>		tovo:		
				1735.64
	•		Such and State .	1773-64
	g g		DEAL DAOICE :	74437
	į.	. 4	•	
	i i i i i i i i i i i i i i i i i i i	٠, ۵		
-	3 Masin	5		•
		2 50		
	3 com			
	- Same			
				HER 06152
	,			11611 00 102

	T /
40781 Primar	12 In
-	
HERCULES OFFS	SHORE CO.
MARINE REPAIR MARINE OPERAT	
DRDER No. 4803	CUSTOMER P.O.
S-15-95	C SILLING ADDRESS
A COMPLETION DATE	S BILLING ADDRESS T O CITY AND STATE
E DEPARTURE DATE	M PHONE HUMBER
NAME ETTIIS	R BORK AUTHORISED BY BOY AUTHORISED BY
LOX SISTH	STOCK MATERIAL YES NO
Claudio Duarte	IF YES, COMPLETE STOCK MATERIAL TRANSPER TICKET
YES	OUTSIDE SERVICES IF YES, LIST YES NO
GAS PREZING NO [] CENTIFICATE REQUIRED NO []	
HAUL OUT FOR INSPECTION AND REPAIR YES NO	
ON WAYS DATE:	
	NUMBERS
1 Strip 4 blow	
	· · · · · · · · · · · · · · · · · · ·
2 ritrogen surge	
3	
<u></u>	
4	
5	
6	
7	
7	
8	

HER 06153

_ Date: _

10

Signed: __

THIS SHALL SERVE AS YOUR AUTHORIZATION TO PROCEED WITH THE ABOVE.

HAZARDS COMMUNICATION STANDARD

OSHA 1910.1200

EXPLOYEE HAZARDOUS MATERIALS TRAINING PROCEAN

Date 0-15-5	•	THAINING PROCEAH
Plant Her Cular		Supervisor Carola Ca
Area Gas Free D		Client Safety
Ett=113	POLK .	
The following ligand		
working in this area	materials are consid	iered to be hexardous to the emp
CYCLOHEYANT	₽ % ţ	to the emp
PANE		
The employees assigned	to york !-	have been informed of the hazar
materials in this	to work in this area	have been informed of the
area	l, the hazarda	or the hazar
Of hear a	media they pr	CBERP PA LL
. or mazarda listed, the	Brokenst	to the workers, the loca
. or mazarda listed, the	Brokenst	to the workers, the loca
it is located, and proc	protective equipment	that has been provided and w
it is located, and proc	protective equipment	that has been provided and w
it is located, and proc	protective equipment	that has been provided and w
it is located, and proc I have received the etrai form.	protective equipment	to the workers, the loca
it is located, and proc	protective equipment edures to be followed ining listed above and	that has been provided and w
it is located, and proc I have received the etrai form.	protective equipment	that has been provided and win case of an accidental exposure will so designate by signing to
it is located, and proc I have received the etrai form.	protective equipment edures to be followed ining listed above and	to the workers, the local that has been provided and will so designate by signing to
it is located, and proc I have received the etrai form.	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposure will so designate by signing to
it is located, and proc I have received the etrai form.	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposure will so designate by signing to
it is located, and proc I have received the trai form. NAME	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposured will so designate by signing to NAME BADCE
it is located, and proc I have received the etrai form.	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposure will so designate by signing to
it is located, and proc I have received the trai form. NAME	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposured will so designate by signing to NAME BADCE
it is located, and proc I have received the trai form. NAME	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposured will so designate by signing to NAME BADCE
it is located, and proc I have received the trai form. NAME	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposured will so designate by signing to NAME BADCE
it is located, and proc I have received the trai form. NAME	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposured will so designate by signing to NAME BADCE
it is located, and proc I have received the trai form. NAME	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposured will so designate by signing to NAME BADCE
it is located, and proc I have received the trai form. NAME	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposured will so designate by signing to NAME BADCE
it is located, and proc I have received the trai form. NAME	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposured will so designate by signing to NAME BADCE
it is located, and proc I have received the trai form. NAME	protective equipment edures to be followed ining listed above and	that has been provided and win case of an accidental exposured will so designate by signing to NAME BADCE

CYCLOHEXANE, 98%

DANGER!

EXTREMELY FLAMMABLE - VAPORS MAY IGNITE EXPLOSIVELY. POSSIBLE ASPIRATION HAZARD.

DANGER: CONTAINS BENZENE · CANCER HAZARD. Benzene is a known human carcinogen · overex-posure may create cancer risk, blood changes or chromosome changes. Benzene has caused fetal death in animals.

PRECAUTIONS:

Keep away from heat, sparks and flame. Keep container closed. Use with adequate ventilation. Avoid contact with eyes, skin or clothing. Wash thoroughly after handling. Launder contaminated clothing before reuse. Do not swallow. May be aspirated into the lungs.

FIRST AID

In case of contact, flush eyes with water. Flush skin with water for 15 minutes. If inhaled, remove from exposure. If breathing is difficult, give oxygen, seek medical attention. If swallowed, do not induce vomiting. Seek immediate medical assistance. NOTE TO PHYSICIAN: Gastric lavage using a cuffed endotracheal tube may be performed at your discretion.

FOR ADDITIONAL INFORMATION, SEE MATERIAL SAFETY DATA SHEET.

MANUFACTURED BY
PHILLIPS 66 COMPANY
A SUBSIDIARY OF PHILLIPS PETROLEUM COMPANY
BARTLESVILLE, OK 74004
UNITED STATES OF AMERICA

FORM 12503-S 12-89

MARINE SERVICES CORPORATION

P. O. Drawer O . Freeport, Texas 77541

INVOICE NO. :

3099-95

DATE

August 30, 1995

Job No.

4802B-1

Location

Freeport

TO:

FOR:

BASF

602 Copper Road Freeport, TX 77541 PLEASE REMIT PAYMENTS TO:

11011 RICHMOND

SUITE 500 HOUSTON, TX. 77042

Terms

: Net 30

PO#F91392

Service to ETT113 as follows:

Nitrogen purge

\$2,806.50

Labor: Leadman 4 0/T

@ 48.00

1 3 3 1 1 3 4 4

192.00 177.00

4 O/T @ 44.25 Journey

Marine chemist

300.00

TOTAL AMOUNT DUE

\$3,475.50

ARRIVED: 8/15/95 5:30/p.m. COMPLETED: 8/15/95 9:30 p.m.

PHONE: (409) 233-6371

HER 06156

MARINE SERVICE CORP FREEPORT, TEXAS	المناه ا	احا	i :	l :	į	i i !		i		i i i	. ! !	Ţ
FOREMAN'S DAILY TIME REPORT) in d	\(\frac{1}{2}\)										O T A
JOB NO 4802 B DATE 8-15-95 CLASS NO. ETT 113	introgen purge	back problems										H O U R S
ž.								· -				
7					<u> </u>	·			:			
- G												
-	_										 	
49 GABRIEL DELAROSA	14											4
										<u></u>		
·												:
73 RICHARD RODRIGUES	47											- 1
	1/						<u> </u>					4
	-											
TOTAL HOURS									HE	 R 061	57	8
BIGNED EXT	ODED AND ENDED	<u> </u>	<u> </u>	<u>l</u>	<u> </u>		APPROVEC	<u> </u>	<u> </u>		<u> </u>	

JOB NO. 11802		
	ETA	
CUSTOMER DINIE CArries	DATE/TIME ARRIVALS/ DATE/TIME STARTEDS/ DATE/TIME COMPLETED PED 300	S-80- 045
PRODUCT CYCLOHEYANE	DATE/TIME STARTED	55° 8 00 4
DISPOSAT AMOUNT	DATE/TIME COMPLETED_	
DISPOSAL AMOUNT AMOUNT STRIPS CLEANING INSTRUCTION BY:	10.30n	
	BY:	
		•
OVERTIME AUTHORIZED BY:		
BARCE INSPECTED BY: BARCE RELEASED TO:	DATE/TIME:	
BARGE RELEASED TO:	DATE/TIME.	
DECEMBELL OPENED: YES WAND CLOSED BY		
BELOW DECK CARCO PIPELINE: BLIND OPEN YES	NO CLOSED BY	10
DECY CHESK WATER	LEGSED BY NEW CYC	:ET
DECK CHECK VALVE OPENED: YES_MA_NOCL	OSED BYNEW GASKET	. ₁₀
DECK CHECK VALVE OPENED: YES NO CLOS DECK HEADER BLINDS OPEN: YES NO CLOS DECK HEADER DRAIN PLUC OPEN: YES NO CLO	ED BY WEW CASKET	NO
DECK HEADER DRAIN PLUC OPEN: YES NO CLO	YES	. 10
VAPOR RECOVERY HEADER OPENED: YES NO C	TOSTO DE	
RUST SCALE: YES NO.	TOSED ST. S/2/4 NEW CYSKET	<u> </u>
RUST SCALE: YES NO WASHED OUT BUT	CKETED OUT	. 30
MIMBER OF CARGO TANKS 3	The state of the s	
ALIE GOD		· · · · · · · · · · · · · · · · · · ·
DRIP PANS STRIPPED: YES NO	E FRESSURE TEST DATE:	
DRIP PANS STRIPPED: YES NO	· ·	
PIPELINE WASHED: OF PIPELINE BLOWN AND DEP	OVERCASTCLOUDY CLE	سسيد و
PIPELINE WASHED: OF PIPELINE BLOWN HOW PIPELINE BLO	ELINE SUMPS INSPECTED OUA - TO	,
		
ODS: YES NO SAFETY EQUIP	MENT USED:	
(3) 大天天大学的东西的大学的大学的大学大学的大学的大学的大学的大学的大学的大学的大学的大学的大学的大	***	
WAR MAAA	***************************************	******

WORK SCOPE

HER 06158

DECLARATION OF INSPECTION PRIOR TO BULK CARGO TRANSFER

VESSELS	Ett=1/3			
, ,	DINE CAYNOC	·	· .=	
TRANSFER FACILITY	Horcues MAS		4	
LOCATION	FREEPORT TX.	- 	i	
			· — — —	
The following list refers on reverse). The spaces adja- been met.	s to requirements set forth in detail is scent to items on the list are provided	n 33 CFR 156.150 ar to indicate that th	d 46 CFR	t 35.35-30 (printed l requirement ha
		DEL	VERER	RECEIVER
I. Communication System	n/Language Fluency (156.120) (m) (p	» <u> </u>		
· 2. Warning Signs and re-	d Warning Signais. (35.35-30)	<u>i</u>		
3. Vessels Moorings, (156.	.120 (a))			
4. Transfer System Align	ment. (156.120 (d))	ļ 		
5. Transfer System; unus	ed components. (156.120 (e))	·		
6. Transfer Systems; fixed	d piping. (156.120 (f))			
7. Overboard Discharges/	Sea Suction Valves. (156.120 (g))			
8. Hoses or Loading Arms	e condition. (156.120 (2) (156.170)		~	
9. Hoses; length and supp	port. (186.120 (b) (e))	ļ		
10. Connections. (186,130)	··			
11. Discharge Containment	Systems. (156.120 (j) (l))	ļ <u> </u>		
12. Scappers or Draine. (1	86.130 (k))		~	
13. Emergency Shudown (1	(65.120 (n)		ستر	
* 14. Repair Work Anthorin	ution. (88.36-80)	N,	Α	N/A
* 15. Boiler and Galley Fire	e Salety, (35.36-30)	N	A	N/A
* 16. Fires or Open Flames	(35.35-30)	<u>N</u>	Α	N/A
17. Lighting (sunset to sur	arise). (186.120 (t))	-		
* 18. Safe Smoking Spaces.	(35.25-30)	<u> </u>		
19. Spill and Emergency s	thntdown procedures. (156.120 (q))			
20, Sufficient Personnel ((156.120 (o) (a))			
21. Transfer Conference. ((186.120 (q))			
22 Agreement to begin tr	ansfer. (150.120 (r))			
I do certify that I have p on reverse and that opposite e	personally inspected this facility or versets of them I have indicated that the	sel with reference to regulations have been	the requirements	draments printed
Person in Charge Receiving C	Onit	True	Ther	♣ DATE
Clause Suate	Ecrem	40		252 9: ccA
Person in Charge Delivering	Unit PUEL PE	RSON	: 	<u>. </u>
Chamber Din	- La		·	
TIME COMPLETION C-12	- GC M: MAD.			HER 0615

[&]quot; Bules and Regulations for Tank Vessals.

יטא ווטב:	4802	B cuerchen:	BASE	EARLES ETT 113
د ماد متدردوان م	,			-
LORDAN				<u> </u>
	<u>ښ ۵/۳</u>	P 51.75		-
PERMIT		e aa.so		
-	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	£ 40.00		165
POURTIE		e 31.00		
	O/r_	H 44.25		177
	•	(2) "不被"大"。 "一"是一个"我们"。	•	
DESTORAT	·:	gal 0 .	25	
	760	en e	-	0 = 30 =
ervifektat.		bj ne 50.s	_50	30a
CHECK MA	TENTAL:	brne 30 s		
				•
UŽUIP:	00	1. 1. 克斯·克 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		
	COMPRESSOR	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	44.00	
	ATR FOUNDS	φ <u>α συν</u> φούς συναμένης φουστορικής το μεταξούς συναμένης συναμέν	5.00	
	FORESCIENT	_ 	26.60	<u> </u>
	TUCHOAT	<u> </u>	00.00	***
	SHAM REC		60.00	
	VACUUM		10.00	
	HVMD INDEE		10.00	
	LIBELDING PACHINE		15.00	
	Charactericker	<u> </u>	50,00	»
	Ciane -	e	110.00	
	PLATIND TRUCK	 #	20.00	*** *** ****
	of CAS Fund	Francis Commence	14.00	·····
	in duapping ba	·re	12.00	والمراجع المراجع المرا
	មានស្រុកជារាវា	0	10.00	
	4" ELECT PURE	<u>e</u>	15.00	
	Project march	e de la companya de l	15.00	
	commic rac	9	ŭ. 0 0	
	HAUL OUT	Land Mark Mark Strain Com	100.00 / 12cy	
រពសម្រាធ់:		COMPLESSED:	DEPARTO:	
na konstitue		TOVO:	·	<u> </u>
		an and the second s	•	4
	· .			669.
	Q.		TOPAL INVOICE :	

RICHARD WIND OWN PAPE THE PAPE WASH WA	TI3-52	a-64119	MARINI	E CHEMIST CERTI SERIAL NO. G	
WIND THE TOTAL CONTROL OF THE CONTRO	RICHARD		HERCULES		
LETTING BOTHON SAR SCO TRANKS NO 1 2 13 3 NOT SAFE FOR WARKERS ATMOSPHERIC TEST OF LEL LESS THAN 6 % Q WING & RINKE TRANS SIDUAL DUT BY ENTIRED WING & RINKE TRANS SIDUAL DUT BY ENTIRED WING & RINKE TRANS SIDUAL DUT BY ENTIRED WIND & RINKE TRANS SIDUAL DUT BY ENTIRED WIND & RINKE TRANS SIDUAL DUT BY ENTIRED WIND THEY (TANK SIDUAL DUT BY ENTIRED WIND THE STATE OF TH	<u> </u>		TANK BARGE		
ATTIMISENTATION BETWEEN THE CONTRIBUTION OF THE STANDARD AND THE STANDARD	N/A (N) Last Three (3) Cargoes				21:00
LESS THAN 6% Q WINDS TREET SHOULD NOT BE ENTERED UNITED THEY SHOULD NOT BE ENTERED TO SHOULD NOT BE ENTERED THE SHOULD NOT BE ENTERED. UNITED THE SHOULD NOT BE ENTERED THE SHOULD NOT BE E	CAR 60	TANKS No 1,2 \$3	NOT	SAFE FOR WOR	KERS
IN TREAT LINE SEEN UGNINATED \$ CHECKED In recovert of allow physician constitutes provide can rive of visions with the second of the second o					
In the event of all y, physical prostores prints, co. or gos of kinner y, plure in grows that have not been real. ON LEGISTATION SETS on the large y duals of recognitive sets of the prints of the p					
If a fine-event of airy physican or atmospheric cranges atherse vigilization; the above spaces or d in any doubt immediately stop a "york and contact the undersigned follower cheeps! QUALIFICATIONS: Movement of vessels from original location, transfer of ballast, or manipulation of valves or closure equipment leading to after conditions in place lines, tanks or compartments subject to gas accumulation, unders spacelloadly appreved in this Certificate, requires inspection and endorsement or release of certificate for the spaces os enfected. All lines, years, heading colls, valves, and similarly enclosed appurtenances shall be considered "not safe" unless otherwise specifically designated. STAMDARD SAFE POR WORKERS, Means that in the compartment or space so designated, (a) the oxygen content of the atmosphere is at least 19.5 percent by volume, and this, (b) locis materials in the atmosphere are within permissible concentrations; and this, (c) the requirements of producing taxic materials under existing atmospheric conditions while maintained as directed on the Marine Chemist's Certificate. NOT SAFE FOR WORKERS, Means that in the compartment or space so designated, the requirements of Sate for Workers have not been met. ENTER WITH RESTRICTIONS. Means that in the compartment or space so designated, eithy for work may be made only if conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment or space so designated, why for work may be made only if conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment or space so designated, they for work may be made on of conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment so designated (a) oxygen content of the atmosphere is allowed by percent by volume, with the exception of inerted spaces or where setternal hot work is to be performed, and that, (b) the con		UNAL THEY	HAVE SEEN VEH	nurated & CHECK	££.
If a fine-event of airy physican or atmospheric cranges atherse vigilization; the above spaces or d in any doubt immediately stop a "york and contact the undersigned follower cheeps! QUALIFICATIONS: Movement of vessels from original location, transfer of ballast, or manipulation of valves or closure equipment leading to after conditions in place lines, tanks or compartments subject to gas accumulation, unders spacelloadly appreved in this Certificate, requires inspection and endorsement or release of certificate for the spaces os enfected. All lines, years, heading colls, valves, and similarly enclosed appurtenances shall be considered "not safe" unless otherwise specifically designated. STAMDARD SAFE POR WORKERS, Means that in the compartment or space so designated, (a) the oxygen content of the atmosphere is at least 19.5 percent by volume, and this, (b) locis materials in the atmosphere are within permissible concentrations; and this, (c) the requirements of producing taxic materials under existing atmospheric conditions while maintained as directed on the Marine Chemist's Certificate. NOT SAFE FOR WORKERS, Means that in the compartment or space so designated, the requirements of Sate for Workers have not been met. ENTER WITH RESTRICTIONS. Means that in the compartment or space so designated, eithy for work may be made only if conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment or space so designated, why for work may be made only if conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment or space so designated, they for work may be made on of conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment so designated (a) oxygen content of the atmosphere is allowed by percent by volume, with the exception of inerted spaces or where setternal hot work is to be performed, and that, (b) the con				_	
If a fine-event of airy physican or atmospheric cranges atherse vigilization; the above spaces or d in any doubt immediately stop a "york and contact the undersigned follower cheeps! QUALIFICATIONS: Movement of vessels from original location, transfer of ballast, or manipulation of valves or closure equipment leading to after conditions in place lines, tanks or compartments subject to gas accumulation, unders spacelloadly appreved in this Certificate, requires inspection and endorsement or release of certificate for the spaces os enfected. All lines, years, heading colls, valves, and similarly enclosed appurtenances shall be considered "not safe" unless otherwise specifically designated. STAMDARD SAFE POR WORKERS, Means that in the compartment or space so designated, (a) the oxygen content of the atmosphere is at least 19.5 percent by volume, and this, (b) locis materials in the atmosphere are within permissible concentrations; and this, (c) the requirements of producing taxic materials under existing atmospheric conditions while maintained as directed on the Marine Chemist's Certificate. NOT SAFE FOR WORKERS, Means that in the compartment or space so designated, the requirements of Sate for Workers have not been met. ENTER WITH RESTRICTIONS. Means that in the compartment or space so designated, eithy for work may be made only if conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment or space so designated, why for work may be made only if conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment or space so designated, they for work may be made on of conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment so designated (a) oxygen content of the atmosphere is allowed by percent by volume, with the exception of inerted spaces or where setternal hot work is to be performed, and that, (b) the con					
If a fine-event of airy physican or atmospheric cranges atherse vigilization; the above spaces or d in any doubt immediately stop a "york and contact the undersigned follower cheeps! QUALIFICATIONS: Movement of vessels from original location, transfer of ballast, or manipulation of valves or closure equipment leading to after conditions in place lines, tanks or compartments subject to gas accumulation, unders spacelloadly appreved in this Certificate, requires inspection and endorsement or release of certificate for the spaces os enfected. All lines, years, heading colls, valves, and similarly enclosed appurtenances shall be considered "not safe" unless otherwise specifically designated. STAMDARD SAFE POR WORKERS, Means that in the compartment or space so designated, (a) the oxygen content of the atmosphere is at least 19.5 percent by volume, and this, (b) locis materials in the atmosphere are within permissible concentrations; and this, (c) the requirements of producing taxic materials under existing atmospheric conditions while maintained as directed on the Marine Chemist's Certificate. NOT SAFE FOR WORKERS, Means that in the compartment or space so designated, the requirements of Sate for Workers have not been met. ENTER WITH RESTRICTIONS. Means that in the compartment or space so designated, eithy for work may be made only if conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment or space so designated, why for work may be made only if conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment or space so designated, they for work may be made on of conditions of proper protective equipment, clothing, and then are as specified. SAFE FOR WORKERS, Means that in the compartment so designated (a) oxygen content of the atmosphere is allowed by percent by volume, with the exception of inerted spaces or where setternal hot work is to be performed, and that, (b) the con					
QUALIFICATIONS: Movement of vessels from original location, transfer of baltest, or reamipulation of valves or closure equipment tending to effect conditions in place lines, transfer or compartments easilect to gas accumulation, unless specifically approved in this Certificate, requires inspection and endorsement or release of Certificate for the spaces or affected. All lines, vents, heating coles, valves, and similarly enclosed appurtenances shall be considered "not safe" unless otherwise specifically designated. STANDARD SAFETY DESIGNATIONS (partial list, persphrased from NFPA 308 Subsections 2-3.1 through 2-3.5, and Subsection 6-3.2) SAFEFOR WORKERS, Means that in the compartment or space so designated; (a) the oxygen content of the atmosphere are within permissible concentrations; and that, (c) the residues are not capable of producing toxic materials under existing atmospheric conditions white maintained as directed on the Marine Chemist's Certificate. NOT SAFEFOR WORKERS, Means that in any compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, clothing, and time are as specified. SAFEFOR WORKERS, Means that in the compartment or space so designated, the requirements of Safe for Workers have not bean met. ENTER WITH RESTRICTIONS: Means that in the compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, clothing, and time are as specified. SAFEFOR HOT WORK Means that in the compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, and time are as specified. SAFEFOR HOT WORK Means that in the compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, clothing, and time are as specified. SAFEFOR HOT WORK Means that in the compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, and that (c) increased as a specified. SAFE					
QUALIFICATIONS: Movement of vessels from original location, transfer of baltest, or reamipulation of valves or closure equipment tending to effect conditions in place lines, transfer or compartments easilect to gas accumulation, unless specifically approved in this Certificate, requires inspection and endorsement or release of Certificate for the spaces or affected. All lines, vents, heating coles, valves, and similarly enclosed appurtenances shall be considered "not safe" unless otherwise specifically designated. STANDARD SAFETY DESIGNATIONS (partial list, persphrased from NFPA 308 Subsections 2-3.1 through 2-3.5, and Subsection 6-3.2) SAFEFOR WORKERS, Means that in the compartment or space so designated; (a) the oxygen content of the atmosphere are within permissible concentrations; and that, (c) the residues are not capable of producing toxic materials under existing atmospheric conditions white maintained as directed on the Marine Chemist's Certificate. NOT SAFEFOR WORKERS, Means that in any compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, clothing, and time are as specified. SAFEFOR WORKERS, Means that in the compartment or space so designated, the requirements of Safe for Workers have not bean met. ENTER WITH RESTRICTIONS: Means that in the compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, clothing, and time are as specified. SAFEFOR HOT WORK Means that in the compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, and time are as specified. SAFEFOR HOT WORK Means that in the compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, clothing, and time are as specified. SAFEFOR HOT WORK Means that in the compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, and that (c) increased as a specified. SAFE					
QUALIFICATIONS: Movement of vessels from original location, transfer of baltest, or manipulation of valvee or closure equipment tending to alter conditions in pipe lines, tanks or compartments subject to gas accumulation, unless specifically approved in this Certificate, requires inspection and endorsement or release of Certificate for the space of effected. All lines, vests, heating colls, valves, and similarly enclosed appurtenances shall be considered "not safe" unless otherwise specifically designated. STANDARD SAFETY DESIGNATIONS (partial list, perspirated from NFPA 308 Subsections 2-3.1 through 2-3.5, and Subsection 6-3.2) SAFE FOR WORKERS: Means that in the compartment or space so designated; (a) the oxygen content of the atmosphere is at least 19.5 percent by volume; and that, (b) toxic materials in the atmosphere are within permissible concentrations; and that, (c) the residues are not capable of producing taxic materials under existing atmospheric conditions while maintained as directed on the Marine Chemist's Certificate. NOT. SAFE FOR WORKERS: Means that in the compartment or space so designated, the requirements of Safe for Workers have not been met. ENTER WITH RESTRICTIONS. Means that in the compartment so designated and entering the work may be made only if conditions of proper protective equipment, clothing, and time are as a specified. SAFE FOR HOT WORK: Means that in the compartment so designated (a) oxygen content of the atmosphere is at least 19.5 percent by volume, with the exception of inerted spaces or where external hot work is to be performed; and that, (b) the concentration than permitted by (b) above under existing atmosphere is below 10 percent of the lower faminable limit, and that (c) the residues are not capable of producing a higher concentration than permitted by (b) above under existing atmosphere is below 10 percent of the ower tammable limit, and that (c) the residues are not capable of producing a higher concentration than permitted by (b) above under existing atmospher	<i>\$</i>				
elter conditions in pipe lines, tanks or compartments subject to gas accumulation, unless specifically designated appurtenances shall be considered "not safe" unless otherwise specifically designated. STANDARD SAFETY DESIGNATIONS (partial list, paraphrased from NFPA 306 Subsections 2-3.1 through 2-3.5, and Subsection 6-3.2) SAFE FOR WORKERS: Means that in the compartment or space so designated; (a) the corporation of the atmosphere is at least 19.5 percent by volume; and that, (b) toxic materials in the atmosphere are within permissible concentrations; and that, (c) the residues are not capable of producing toxic materials under existing atmospheric conditions white maintained as directed on the Marine Chemist's Cardificate. NOT SAFE FOR WORKERS: Means that in the compartment or space so designated, the requirements of Safe for Workers have not been met. ENTER WITH RESTRICTIONS: Means that in any compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, clothing, and time are as specified. SAFE FOR HOT WORK: Means that in the compartment so designated: (a) oxygen content of the atmosphere is at least 19.5 percent by volume, with the exception of inerted spaces or where external hot work is to be performed; and that, (b) the concentration of flammable materials in the atmosphere is below 10 percent of the lower flammable limit; and that (c) the residues are not capable of producing a higher concentration than permitted by (b) above under existing atmospheric conditions in the presence of fire, and while maintained as directed on the Marine Chemist's Certificate; and further, that (g) all adjaces appears spaces containing or having contained flammable or combustible materials have been cleaned sufficiently to prevent the spread of fire, or are satisfactority inerted, or, in the case of fuel tanks or lube oil tanks, or engine room of fire room bilges, have been treated in accordance with the Marine Chemist's requirements. NOT SAFE FOR HEPAIR YARD ENTRY:	of the above s	prices or if in any doubt immediately sto	op a " work and contact the undersign	ed Marine Chemist in 1995 Con St	
NOT SAFE FOR WORKERS: Means that in the compartment or space so designated, the requirements of Safe for Workers have not been met. ENTER WITH RESTRICTIONS: Means that in any compartment or space so designated, entry for work may be made only if conditions of proper protective equipment, clothing, and time are as specified. SAFE FOR HOT WORK: Means that in the compartment so designated: (a) oxygén content of the atmosphere is at least 19.5 percent by volume, with the exception of inerted spaces or where external hot work is to be performed; and that, (b) the concentration than permitted by (b) above under existing atmospheric conditions in the presence of fire, and what in the residues are not capable of producing a higher concentration than permitted by (b) above under existing atmospheric conditions in the presence of fire, and what in the permitted as directed on the Marine Chemist's Certificate; and further, that, (d) all adjacent spaces containing or having contained flammable or combustible materials have been cleaned sufficiently to prevent the spread of fire, or are satisfactionly inerted, or, in the case of fuel tanks or lube oil tanks, or engine room or fire norm bilges, have been treated in accordance with the Marine Chemist's requirements. NOT SAFE FOR HOT WORK: Means that in the compartment so designated, the requirements of Safe for Hot Work have not been met. SAFE FOR REPAIR YARD ENTRY: Means that the compartments and spaces of the flammable cryogenic liquid carrier so designated; (a) have been tested by sampling at remote sampling stations, and results indicate the atmosphere tested to be above 19.5 percent oxygen, and less than 10 percent of the lower flammable limit, or (b) are inerted. CHEMIST'S ENDORSEMENT. This is to certify that it have personally determined that all spaces in the foregoing its are in accordance with NFPA 306 Control of Gas Hazard's on Vessels and have found the condition of each to be in accordance with its assigned designation.	alter conditions inspection and elements and elements and elements are STANDARD SAFETY SAFE FOR WORKER in the atmosphere are	in pipe lines, tanks or compartments sub indorsement or release of Certificate for the hell be considered "not safe" unless of he / DESIGNATIONS (parial list, paraphrased from NF S; Means that in the compartment or space so design within perhissible concentrations; and that, (c) the re	ject to gas accumulation, unless spe he spaces so affected. All lines, vents revise specifically designated. PA 308 Subsection 2-3.1 through 2-3.5, and s sect (a) the covern content of the strosofters is	cifically approved in this Certificat , heating coils, valves, and similar Subsection 6-3.2) at least 195 percent by volume; and that (b) (to, requires ly enclosed loxic materials
the Marine Chemist's requirements. NOT SAFE FOR HOT WORK: Means that in the compartment so designated, the requirements of Safe for Hot Work have not been met. SAFE FOR REPAIR YARD ENTRY: Means that the compartments and spaces of the flammable cryogenic liquid carrier so designated; (a) have been tested by sampling at remote sampling stations, and results indicate the atmosphere tested to be above 19.5 percent oxygen, and less than 10 percent of the lower flammable limit, or (b) are inerted. CHEMIST'S ENDORSEMENT. This is to certify to that I have personally determined that all spaces in the foregoing its are in accordance with NFPA 306 Control of Gas Hazard's on Vessels and have found the condition of each to be in accordance with its assigned designation. The determined accordance with the first personal to the condition of each to the in accordance with its assigned designation.	NOT SAFE FOR WOR ENTER WITH RESTA time are as specified. SAFE FOR HOT WOF or where external hot (c) the residues are no directed on the Marie	FIKERS: Means that in the compartment or space as BCTIONS: Means that in any compartment or space BC: Means that in the compartment so designated: (a work is to be performed; and that, (b) the concentra t capable of producing a higher concentration than p to Chamiet's Continents and further that (it all and and its or the concentration).	so designated, entry for work may be made only) oxygén content of the atmosphere is at least 15 stion of flammable materials in the atmosphere ermitted by (b) above under existing atmosphere incomt expect contained.	if conditions of proper protective equipment 5. percent by volume, with the exception of it is below 10 percent of the lower flammable conditions in the presence of fire, and white flammable or combustible materials have	nerted spaces limit, and that maintained as been cleaned
ungerstands conditions and limitations under which it was issued." issued subject to compliance with all qualifications analynistructions.	the Marine Chemist's NOT SAFE FOR HO! SAFE FOR REPAIR Y Sampling stations, and CHEMIST'S ENDOR: Vessels and have fou	requirements. I WORK: Means that in the compartment so designs that the compartment so designs that the compartments and spart results indicate the atmosphere tested to be above SEMENT. This is to certify that I have personally defined the condition of each to be in accordance with it are recept of this Certificate under Section 2-6 of NFPA 3.	ated, the requirements of Safe for Hot Work have laces of the flammable cryogenic liquid carrier s e 19.5 percent oxygen, and less than 10 percent termined that all spaces in the foregoing list are is assigned designation. This Certificate is based on condition	e not been met. O designated: (a) have been tested by sample tof the lower flammable limit, or (b) are inerin accordance with NFPA 306 Control of Gi	oling al remote ried: as Hazands on

20M-2-88

NOTE: THIS CERTIFICATE IS VALID ONLY ON MARINE VESSELS

CUSTOMER COPY

Printed in U.S.A.

713-520-5419		HEMIST CERTIFICATI SERIAL NO. G 28737
RICHARD	HERCULES	ISAUG 95
En - 113	TANK BARGE	HERCULES
Vocani (A)	Type of Vaporal LEL-() - VISUAL	Specific Location of Vessel 21:00
Last Three (3) Cargoes	Tests Performed	Time Survey Completed
CORGO TANKS No 1,2	193 NOT SI	IFE FOR WORKERS
Atmospheri	C TEST OF LEL	N -
MINIOPHILE		\\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\
	LESS TIM 6% U	· · · · · · · · · · · · · · · · · · ·
. 7		· · · · · · · · · · · · · · · · · · ·
	23 *-	
WING &	RIKE TANKS SIDULD NOT	be emigren
UN DL T	ter thre seen venti	nted & checked

	······	
· .	· · · · · · · · · · · · · · · · · · ·	
*	·	
	hanges adversely affecting the STANDARD SAFETY Did ate vision allowers and contact the understaned Mar	
QUALIFICATIONS: Movement of vessels from or	iginal location, transfer of ballast, or manipulation of	valves or closure equipment tending to
after conditions in pipe lines, tanks or compartr inspection and endorsement or relssue of Certifi appurtenances shall be considered "not safe" u	ments subject to gas accumulation, unless specificall leats for the spaces so affected. All lines, vents, heati nless otherwise specifically designated.	y approved in titls Certificate, requires ng colls, valves, and similarly enclosed
STANDARD SAFETY DESIGNATIONS (pertial list, peraphra SAFE FOR WORKERS: Means that in the compartment or see	used from NFPA 306 Subsections 2-3.1 through 2-3.5, and Subsections on designated (a) the opposite content of the atmosphere is at least	19.5 percent by volume; and that, (b) toxic materials
in the atmosphere are within permissible concentrations; and t as directed on the Marine Chemist's Certificate.	hat, (c) the residues are not capable of producing toxic materials unde	r existing almospheric conditions while maintained
ENTER WITH RESTRICTIONS: Means that in any comparison	it or space so designated, the requirements of Safe for Workers have ent or space so designated, entry for work may be made only if condi-	
or where external hot work is to be performed; and that, (b) if (c) the residues are not capable of producing a higher concent dispense on the Marine Chimist's Carifornia and Authorities	esignaled: (a) oxygen content of the atmosphere is al least 19.5 perce he concentration of flammable materials in the atmosphere is below tration than permitted by (b) above under existing atmospheric conditi- tal, (d) all adjacent spaces containing or having contained flammal thed, or, in the case of fuel tanks or lube oil tanks, or engine room or fire	ons in the presence of fire, and white maintained as the or combustible materials have been cleaned
the Marine Chemist's requirements. NOT SAFE FOR HOT WORK: Means that in the comparime	nt so designated, the requirements of Sale for Hot Work have not be	en met. Jaled: (a) have been tested by sampling at remote
earmaina elabane SMI (PS) IIIS INDICAID the almocobera toster	d to be above 19.5 percent oxygen, and less than 10 percent ersonally determined that all spaces in the foregoing list are in accor- dance with its assigned designation.	dance with NFPA 306 Control of Gas Hazards on
"The undersigned acknowledges receipt of this Certificate under Section 2 understands conditions and initiations under which it was assued."	and the second s	- WI
	Signed	1/200 log/

20M-2-68

ERIC MOORE MARINE CHEMIST CERTIFICATE 713-520-5479 SERIAL NO. G 28737 HERCULES RICHARD 15 AUG 95 dank barge HERCULES - VISUAL 1:00 1293 TANKS No SAFE FOR WORKERS <u> Snr.60</u> NOT OZLEL amospheric test LESS NINU 6% WING & KILKE THINKS SIDULD NOT BE ENTERED BEEN UGNALATED & CHECKED UNDL THEY HAVE J हो gingthe event of any physical og atmospheric changes adversely affecting the STANDARD SAFETY DESIGNATIONS assigned कि of the above spaces, or it in any doubt i mined atery stop all work and contact the ondersigned Marine Chemist के आहे. QUALIFICATIONS: Movement of vessels from original location, transfer of ballast, or manipulation of valves or closure equipment tendinal alter conditions in pipe lines, tanks or compartments subject to gas accumulation, unless specifically approved in this Certificate, requirements and endorsement or reissue of Certificate for the spaces so affected. All lines, vents, heating colls, valves, and similarly enchappurtenances shall be considered "not safe" unless otherwise specifically designated. STANDARD SAFETY DESIGNATIONS (pertial list, paraphrased from NFPA 306 Subsections 2-3.1 through 2-3.5, and Subsection 6-3.2) SAFE FOR WORKERS: Meens that in the compartment or space so designated: (a) the oxygen content of the atmosphere is at least 19.5 percent by volume; and that, (b) toxic materials in the atmosphere are within permissible concentrations; and that, (c) the residues are not capable of producing toxic materials under existing atmospheric conditions while maintained as directed on the Marine Chemist's Certificate. NOT SAFE FOR WORKERS: Means that in the compartment or space so designated, the requirements of Safe for Workers have not been met. ENTER WITH RESTRICTIONS: Means that in any compartment or space so designated, entry for work may be made only if conditions of proper protective equipment clothing, and

SAFE FOR HOT WORK: Means that in the compartment so designated: (a) oxygen content of the atmosphere is at least 19.5 percent by volume, with the exception of inerted spaces or where external hot work is to be performed; and that, (b) the concentration of flammable materials in the atmosphere is below 10 percent of the lower flammable limit; and that, (c) the residues are not capable of producing a higher concentration than permitted by (b) above under existing atmospheric conditions in the presence of fire, and while maintained as directed on the Marine Offernist's Certificate; and further, that, (d) all adjacent spaces containing or having contained flammable or combustible materials have been cleaned sufficiently to prevent the spread of fire, or are satisfactority inerted, or, in the case of fuel tanks or lube oil tanks, or engine room or fire room bilges, have been treated in accordance with the Marine Chemist's requirements.

NOT SAFE FOR HOT WORK: Means that in the compartment so designated, the requirements of Safe for Hot Work has

SAFE FOR REPAIR YARD ENTRY: Means that the compartments and spaces of the flammable cryogenic liquid carrier so designated: (a) have been tested by sampling at remote sampling stations, and results indicate the atmosphere tested to be above 19.5 percent oxygen, and less than 10 percent of the lower flammable limit, or (b) are merted.

CHEMIST'S ENDORSEMENT. This is to certify that I have personally determined that all spaces in the toregoing list are in accordance with NFPA 306 Control of Gas Hazards on Vessels and have found the condition of each to be in accordance with its assigned designation.

The undersigned acknowledges receipt of this Certificate under Section 2-5 of NEPA 305 and inderstands conditions and limitations under which it was issued."

20M-2-88

This Certificate is based on consued subject to compliance

NOTE: THIS CERTIFICATE IS VALID ONLY ON MARINE VESSELS

Printed in U.S.A.

CAMACIE NO (24)

1 . HERCULES OFFSHORE CO. MARINE OPERATIONS FACILITY CUSTOMER P.O. - 95 USTO D હેડ A M E R STOCK MATERIAL YES IF YES, COMPLETE STOCK MATERIAL TRANSFER TICKET OUTSIDE SERVICES YES □ NO YES | GAS FREEING NO CERTIFICATE REQUIRED HAUL OUT FOR INSPECTION AND REPAIR NO 🗆 YES 🗍 ON WAYS DATE: ON WAYS ITEM NUMBERS Respirator Filters, Two Consealls, Two

8

ERIC L. MOORE MARINE CHEMIST 713-520-5479 409-297-7699 P.O. BOX V FREEPORT TX 77542

INVOICE

Invoice No. 08161 Invoice Date 08/16/95

HERCULES P.O. DRAWER O FREEPORT TEXAS 77541

PO NUMBER XXXXX

RICHARD

The proof of the second of the second

28737

ETT-113

DESCRIPTION	TAXABLE	AMOUNT
CHEMIST CERTIFICATE OF INSPECTION ON THE VESSEL ETT-113 AT HERCULES IN FREEPORT TEXAS ON 15 AUG 95, 21:00.		250.00
RECEIVED		
VITE 57 VECD		
HERCULES OFFSHORE MARINE DIVISION		بيمي
	*	
Amount Paid 0.00 Statement	Subtota	d 250.00
0 - 30 days 31 - 60 61 - 90 90 plus Total Due 2,000.00 1,750.00 750.00 2,000.00 6,500.00	тота	L \$250.00

4802

HER 06165